

CONTENTS

INTRODUCTION	1
1. WHAT IS ROUGHNESS?	3
1.A Scratches and Digs	3
1.B Polishing Marks and Microirregularities	5
1.C Machining Marks and Grating Grooves	5
1.D Dust Particles and Particulates	6
2. HOW DO WE SEE ROUGHNESS?	7
2.A Observing Light Scattered by the Surface	7
2.B Using a Differential Interference Contrast (Nomarski) Microscope	7
2.C Using Electron Microscopes	10
2.C.1 Transmission Electron Microscope (TEM), 10	
2.C.2 Scanning Electron Microscope (SEM), 10	
2.C.3 Scanning Transmission Electron Microscope (STEM), 11	
2.C.4 Scanning Tunneling Microscope (STM), 11	
3. HOW DO WE MEASURE ROUGHNESS?	13
3.A Surface-Profile Measurements	14
3.A.1 Noncontact Methods, 14	
3.A.2 Contact Methods, 18	
3.B Area Topography Measurements	22
3.C Determining Roughness from Scattering Measurements	24
3.C.1 Total Integrated Scattering (TIS), 24	
3.C.2 Angle-Resolved Scattering (ARS), 27	
3.C.3 Bidirectional Reflectance Distribution Function (BRDF), 30	
3.D Comparison of Methods for Determining Roughness	31

4. SCATTERING THEORIES AND SURFACE STATISTICS	38
4.A Root-Mean-Square and Average Roughness, and Root-Mean-Square Slope	38
4.A.1 Root-Mean-Square Roughness, 38	
4.A.2 Average Roughness and Ten-Point Height, 39	
4.A.3 Root-Mean-Square Slope, 39	
4.A.4 Statistical Sampling of Surface Roughness, 41	
4.B Height and Slope Distribution Functions, Skewness, and Kurtosis	42
4.B.1 Height Distribution Function, 42	
4.B.2 Skewness and Kurtosis, 43	
4.B.3 Slope Distribution Function, 44	
4.C Autocovariance Function, Correlation Length, and Surface Spatial Wavelength	44
4.D Power-Spectral-Density Function	48
4.E Total Integrated Scattering	50
4.F Angle-Resolved Scattering	53
4.G Mie Scattering from Particulates	55
5. STATISTICS FOR SELECTED SURFACES	57
6. SCATTERING IN THE ULTRAVIOLET AND X-RAY REGIONS	69
7. SCATTERING IN THE INFRARED	73
8. CLEANING AND INSPECTION OF SURFACES	75
PLATES	81
APPENDIX A. ENGLISH AND METRIC UNITS	89
APPENDIX B. MEASUREMENT FACILITIES	90
REFERENCES	98
INDEX	107